

Figure 1 – View of subject site from Church Street (taken August 11, 2020)



Figure 2 – View of adjacent condominium complex (taken August 11, 2020)



 $\textit{Figure 3-View of existing access off West 3}^{\textit{rd}} \, \textit{Street along East Branch Rahway River (taken August 11, 2020)}$ 



Figure 4 – View of continued drive sequence along access next to East Branch Rahway River (taken August 11, 2020)



Figure 5 - View of continued drive sequence along access next to East Branch Rahway River (taken August 11, 2020)




Figure 6 View of continued drive sequence along access next to East Branch Rahway River (taken August 11, 2020)

Commuter parking lot is on the left and condominium parking is gated in the background.



Figure 7 – View of commuter parking lot (taken August 11, 2020)



Figure 8 – View of commuter parking lot in relation to back of subject dwelling (on left) – taken August 11, 2020)



Figure 9 – View of parking area behind subject site to be removed due to lack of access easement found (taken August 11, 2020)



Figure 10 - View of parking area behind subject site to be removed due to lack of access easement found (taken August 11, 2020)